


15.STATE HIGHWAY 158 & COUNTY ROAD 615



Intersection Characteristics

Intersection Type: T-Intersection

Control Type: Stop Sign on County Road 615

Speed Limit: 55 mph on State Highway 158 and County Road 615

Number of Lanes: 2 Lanes along State Highway 158 and County Road 615

Roadway Section: Two-way, not divided along State Highway 158 and County Road 615

Roadway Alignment: Straight on all approaches

Average Total Entering Daily Traffic: Approximately 1,310 vehicles

Existing Conditions

This intersection of State Highway 158 and County Road 615 is one of the four HIN intersections that were not located along one of the HIN segments that was in the top five for each Region. The intersection is rural with no lighting present. Pavement markings at the intersection are worn and do not include a stop bar for County Road 615. All crashes reported at the intersection of State Highway 158 and County Road 615 were run off the road crashes, 75 percent of these crashes occurred between dusk and dawn.

Countermeasure Summary

Countermeasures identified for the intersection of State Highway 158 and County Road 615 are recommended to address run-off-the-road and lane departure crashes, T-intersection crashes, and crashes that occur between dusk and dawn.

Countermeasure

Vehicular Countermeasures

General Pavement Markings
 Longitudinal Rumble Strips
 Paved Shoulder
 Safety Edge
 Safety Lighting
 T-Intersection Treatment
 Wider Edge Lines