


13. STATE HIGHWAY 140 – STATE HIGHWAY 297 TO S COUNTY ROAD 121



Existing Conditions

This 3.75-mile segment of State Highway 140 includes one High Injury Network (HIN) road segment that ranks among the top five in the West Region. Over 50 percent of reported crashes were run-off the road or lane departure crashes, likely due to the segment being narrow with no lighting. T-intersections along the corridor are frequent but lack adequate warning signage with guardrails. A fatal crash occurred at the intersection with Main Street, which had both a stop sign and a yield sign on the minor street leg. It is recommended that the yield sign be replaced with a stop sign.

Countermeasure Summary

The countermeasures identified State Highway 140 between State Highway 297 and S County Road 121 are recommended to address T-intersection crashes and run off the road or lane departure crashes.

Countermeasure
Vehicular Countermeasures
General Pavement Markings
Guardrail
Replace Yield Sign with Stop Sign
Safety Lighting
T-Intersection Treatment
Wider Edge Lines